

Oil Field Environmental Incident Summary

Incident: 20160324160012 **Date/Time of Notice:** 03/24/2016 16:00

Responsible Party: MARATHON OIL COMPANY

Well Operator: MARATHON OIL COMPANY

Well Name: BENZ 24-21H

Field Name: BAILEY

Well File #: 16726

Date Incident: 3/24/2016 **Time Incident:** 08:50

Facility ID Number:

County: DUNN

Twp: 146

Rng: 94

Sec: 21

Qtr: SW SE

Location Description:

Submitted By: Jacob Parker

Received By:

Contact Person: Jacob Parker
3172 HWY 22 N
DICKINSON, ND 58601

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	6	Gallons

Recovered	Units
-----------	-------

Followup	Units
4	gallons

Brine

Other

Description of Other Released Contaminant:

Benz 24-21H; near 2nd St NW and 100th Ave NW

Inspected:

Written Report Received: 4/26/2016

Clean Up Concluded: 3/24/2016

Risk Evaluation:

The fluid beneath the flare stack caught fire and self extinguished. Fire stayed within facility boundaries.

Areal Extent:

Mist from flare travel offsite impacting approximately 15000 cubic ft (.34 acres)

Potential Environmental Impacts:

Limited impact to vegetation.

Action Taken or Planned:

Impacted soils were recovered; the impacted vegetation was mowed and clippings were bagged.

Wastes Disposal Location: Waste will be disposed of at R360 landfill.

Agencies Involved:

Updates

Date: 3/24/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 3/30/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 3/30/2016, at 12:02 p.m. Release was to the north of flare pit off location. Impacted area is approximately 150 x 200 ft. Area has been mowed and bagged. Bags are on location in a lined berm awaiting disposal. No remaining impacts seen off location at this time. No further follow-up required.